



NOTES:

1. SPECIAL DESIGN CONSIDERATIONS OR STRUCTURAL REVIEW MAY BE REQUIRED FOR TALLER PLANTER WALLS. STEEL REINFORCEMENT MAY BE NEEDED FOR STABILITY.
2. MAINTAIN 1:6 BATTER FOR WALLS AND 6" MIN. TO TOP OF CURB.
3. BROOM FINISH ALL EXPOSED CONCRETE SURFACES.
4. PROVIDE A $\frac{3}{4}$ " DUMMY JOINT AT 10' O.C. ON SIDES AND TOP. PROVIDE $\frac{1}{2}$ " EXPANSION JOINT AT MAXIMUM 100' O.C.



PLANTER WALL

STANDARD PLAN:
SD-080 LID

DATE: JUNE 2017

CITY ENGINEER APPROVAL: