



**NOTES:**

1. SPECIAL DESIGN CONSIDERATIONS OR STRUCTURAL REVIEW MAY BE REQUIRED FOR TALLER PLANTER WALLS. STEEL REINFORCEMENT MAY BE NEEDED FOR STABILITY.
2. MAINTAIN 1:6 BATTER FOR WALLS AND 6" MIN. TO TOP OF CURB.
3. BROOM FINISH ALL EXPOSED CONCRETE SURFACES.
4. PROVIDE CONTRACTION JOINTS AT 10' O.C. ON SIDES AND TOP. JOINT LOCATIONS SHALL MATCH WITH SIDEWALK JOINTS.

N.T.S.



**CITY OF KELSO**  
DEPARTMENT OF  
COMMUNITY DEVELOPMENT  
& ENGINEERING

**PLANTER WALL**

**CITY ENGINEER APPROVAL: Michael Kardas, P.E.**

x *Michael Kardas*

STANDARD PLAN NO.

**KSD-070-21**  
**LID**

DATE:

**MAY 2021**